star bulletin






Date:	October 20, 2014
Order No.:	S-B-42.10/125
Supersedes:	
Group:	42

SUBJECT: MY-AII, Models AII, Brake Caliper with Mercedes-Benz Brand Cover

- 1 Brake caliper
- 4 Brake linings
- 5 Retaining spring
- 6 Mercedes-Benz logo panel



It is not necessary to remove the clipped-on Mercedes- Benz logo panel (6) to remove/install the brake linings (4) and remove the retaining spring (5). After removing the Mercedes-Benz logo panel (6), the original condition can only be restored by replacing the brake caliper (1).

Figure 1.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Records.

© 2014 Mercedes-Benz USA, LLC. Mercedes-Benz Canada, Inc. Dealer Workshop Services <u>www.MBUSA.com</u> www.startekinfo.com All rights reserved. Reproduction or translation in whole or in part is not permitted without authorization from the publisher. Printed in U.S.A. 1-800-FOR-MERCedes