

—

RECALL Subject : Driver's Frontal Air Bag Inflator May Rupture , 1 INVESTIGATION(S)

Report Receipt Date: FEB 10, 2016
NHTSA Campaign Number: 16V077000
Component(s): AIR BAGS
Potential Number of Units Affected: 136,361

All Products Associated with this Recall ▲

Vehicle Make	Model	Model Year(s)
DODGE	SPRINTER 2500	2007-2014
DODGE	SPRINTER 3500	2007-2014
FREIGHTLINER	SPRINTER 2500	2007-2014
FREIGHTLINER	SPRINTER 3500	2007-2014
MERCEDES BENZ	SPRINTER 2500	2007-2014
MERCEDES BENZ	SPRINTER 3500	2007-2014

Details ▲

3 Associated Documents ▼

Manufacturer: Daimler Vans USA, LLC

SUMMARY:
Daimler Vans USA, LLC (Daimler Vans) is recalling certain model year 2007-2014 Dodge, Freightliner, and Mercedes Benz Sprinter 2500 and 3500 vehicles manufactured July 1, 2006, to July 31, 2014. Upon deployment of the driver's frontal air bag, excessive internal pressure may cause the inflator to rupture.

CONSEQUENCE:
In the event of a crash necessitating deployment of the driver's frontal air bag, the inflator could rupture with metal fragments striking the vehicle occupants potentially resulting in serious injury or death.

REMEDY:
Daimler Vans will notify the Mercedes-Benz and Freightliner owners and Fiat Chrysler will notify the Dodge owners. The respective dealers will replace the driver frontal air bag inflator, free of charge. The manufacturer has not yet provided a notification schedule. Mercedes-Benz and Freightliner owners may contact Daimler Van's customer service at 1-877-762-8267. Dodge owners may contact Fiat Chrysler customer service at 1-800-853-1403.

NOTES:
Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.