



Mercedes-Benz
The best or nothing.

star bulletin



Date: March 26, 2015
Order No.: S-B-27.30/127
Group: 27

**SUBJECT: MY-All, Models with Transmission 722.9 (all serial numbers: 05552226, 07814299, 10141478 and forward)
Transmission Seal Change**

Due to improved noise, vibration and harshness (NVH) behavior of the torque converter, elastomer sealing (Part number A 222 271 00 80) on the bell housing (Figure 1) is no longer necessary. Any 722.9 transmission variants being produced will have the seal removed. New vehicles may arrive with or without the seal. No replacement is necessary for vehicles arriving without a seal.




Figure 1.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Records.