





Date: January 9, 2013

Order No.: S-B-98.00/31

Group: 98

SUBJECT: MY-All, Models All

Cleaning Tin-Plated Surfaces

Prior to painting tin-plated surfaces do the following:

Procedure

- 1. Heat with an infrared portable radiant drying unit for approximately 15 minutes.
- 2. After the surface has cooled sufficiently, clean the area thoroughly with sheet-metal cleaner or degreasing agent.
- 3. Paint with approved painting material.

Reference http://aftersales.mercedes-benz.com, and S-B-98.00/13T (or latest version).

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Records.